




## Replaces Toro TimeCutter 5000 Parts

Zero-Turn Mower with 50in Deck - Model 75750

50in Side Discharge Deck



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro TimeCutter 5000 Parts

Zero-Turn Mower with 50in Deck - Model 75750

50in Side Discharge Deck



| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Order Quantity |
|---------|--------------|--------------|-------------|---------|----------------|
|---------|--------------|--------------|-------------|---------|----------------|

## Belts & Pullies

|    |           |          |                         |   |  |
|----|-----------|----------|-------------------------|---|--|
| 10 | R139-2399 | 139-2399 | V-Belt - Traction Drive | 1 |  |
| 11 | R119-8820 | 119-8820 | Belt                    | 1 |  |

## Spindles

|    |           |                                    |                |   |  |
|----|-----------|------------------------------------|----------------|---|--|
| 20 | R139-3214 | 117-7267,<br>121-0751,<br>139-3214 | Spindle Assy   | 3 |  |
| 21 | R117-7268 | 117-7268                           | Shaft- Spindle | 3 |  |

## Other Parts Available

|    |         |                                                                                                                                                                                                                                                                                                                                |                              |   |  |
|----|---------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------|---|--|
| 30 | R3219-6 | 3219-6                                                                                                                                                                                                                                                                                                                         | Nut - 5/8-18 Gr 8 Hex        | 3 |  |
| 31 | R453011 | 01-166-0100,<br>01-166-0120,<br>01-166-0270,<br>01-166-0500,<br>01-166-0600,<br>01-166-0620,<br>132-4593,<br>2356-3,<br>237-12,<br>24-10-AD,<br>24-11-AD,<br>24-11-BD,<br>24-12-AD,<br>24-12-BD,<br>30-9310,<br>32-8190,<br>3256-24,<br>3256-3,<br>3256-36,<br>3256-4,<br>453011,<br>47-9950,<br>48-9220,<br>513458,<br>7-0052 | Washer - Flat 3/8 SAE Y/Zinc | 1 |  |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



## Replaces Toro TimeCutter 5000 Parts

Zero-Turn Mower with 50in Deck - Model 75750

50in Side Discharge Deck



| Item No | R&R Part No. | OEM Part No.                                                                                                                                                              | Description                     | Qty Req | Order Quantity |
|---------|--------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------|---------|----------------|
| 32      | R323-9       | 01-150-0190,<br>01-150-1540,<br>01-178-0614,<br>107229,<br>20-50-AD,<br>20-50-AGD,<br>30-9430,<br>32105-4,<br>3224-5,<br>323-9,<br>513363,<br>513364,<br>5377,<br>908037P | Bolt - Hex HD 3/8-16 x 1-3/4    | 1       |                |
| 33      | R63-7400     | 63-7400                                                                                                                                                                   | Washer - Rebound                | 3       |                |
| 34      | R104-8301    | 104-8301,<br>104-9301,<br>109-6658,<br>133-7570                                                                                                                           | Locknut - 3/8-16 Nylon Flanged  | 6       |                |
| 35      | R68-2730     | 1-603299,<br>68-2730                                                                                                                                                      | Wheel - Anti Scalp              | 3       |                |
| 36      | R112-3977    | 112-3977                                                                                                                                                                  | Bolt- Shoulder                  | 3       |                |
| 37      | R110-9981    | 110-9981                                                                                                                                                                  | Washer-Plain                    | 1       |                |
| 38      | R115-5059-03 | 115-5059-03                                                                                                                                                               | Mower Blade - High Lift 17.5 in | 3       |                |
| 39      | R138-7276    | 138-7276                                                                                                                                                                  | Arm - Idler                     | 1       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.