



NGK Spark Plug - R7435-10

RN4897



Replaces

Autolite	4051
----------	------

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1