




Replaces Toro Groundsmaster 7210

Parts

Zero-Turn Mower with 72in Deck - Model 30618
Engine



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Groundsmaster 7210

Parts

Zero-Turn Mower with 72in Deck - Model 30618
Engine



| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Order Quantity |
|---------|--------------|--------------|-------------|---------|----------------|
|---------|--------------|--------------|-------------|---------|----------------|

Electrical, Gauges, & Controls

| | | | | | |
|----|------------------|-------------------------------|--------------------------|---|--|
| 20 | R94-6710 | 94-6710 | Fuse-Blade, 2 Amp | 1 | |
| 21 | R218-578 | 218-578, 95-2438 | Fuse - 10 Amp | 2 | |
| 22 | R150812 | 109102, 109355, 218-581 | Fuse - 15 Amp | 1 | |
| 23 | R100-4918 | 100-4918 | Diode | 2 | |
| 24 | R105-0040 | 105-0040 | Cable- Battery- Negative | 1 | |
| 25 | R99-7435 | 99-7435 | Relay - 70 Amp | 1 | |
| 26 | R99-7430 | 99-7430 | Relay - 30 Amp | 2 | |
| 27 | R108-8657 | 108-8657 | Harness-Wire, Seat | 1 | |

Filters

| | | | | | |
|----|------------------|---|-----------------------------|---|--|
| 30 | R108-5194 | 108-5194 | Oil Filter - Hyd | 1 | |
| 31 | R125-8752 | 125-8752 | Filter - Fuel/Oil Donaldson | 1 | |
| 32 | R5000919 | 108-3810, 1083810, 98-9763, 989763 | Baldwin Air Filter Element | 1 | |

Other Parts Available

| | | | | | |
|----|------------------|---|--------------------------------|---|--|
| 70 | R104-8301 | 104-8301, 104-9301, 109-6658, 133-7570 | Locknut - 3/8-16 Nylon Flanged | 1 | |
| 71 | R66-2490 | 66-2490 | Retainer - Battery | 1 | |
| 72 | R3231-5 | 3231-5 | Bolt - Carriage 3/8-16 x 1-3/4 | 1 | |
| 73 | R114-8417 | 114-8417 | Locknut - 7/16-14 Nylon Hx Fl | 2 | |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Groundsmaster 7210 Parts

*Zero-Turn Mower with 72in Deck - Model 30618
Engine*



| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Order Quantity |
|---------|------------------|--|----------------------------------|---------|----------------|
| 74 | R130-2486 | 130-2486, 53-9681 | Mount - Motor | 2 | |
| 75 | R87-5100 | 87-5100 | Washer - Snubbing | 2 | |
| 76 | R324-11 | 3225-8, 324-11 | Bolt - 7/16-14 x 2 3/4 Hx HD GR5 | 2 | |
| 77 | R323-6 | 01-150-0010, 01-178-0608, 20-47-AD, 20-47-AGD, 3224-2, 323-6, 49-3510, 908034P, 908332 | Bolt - Hex HD 3/8-16 x 1 GR5 YZ | 4 | |
| 78 | R93-9164 | 93-9164 | Indicator - Service - Air Filter | 1 | |
| 79 | R2412-130 | 2412-130, 2412-92 | Clamp - Hose 1 5/16-2 1/2 | 2 | |
| 80 | R120-9131 | 120-9131 | Coupling - Flywheel | 1 | |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.