




## Replaces Toro Greensmaster 3100 Parts

SPA Cutting Unit - Models 04445, 04448 & 04450  
Minuteman Roller System



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Greensmaster 3100 Parts

SPA Cutting Unit - Models 04445, 04448 & 04450  
Minuteman Roller System



| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Order Quantity |
|---------|--------------|--------------|-------------|---------|----------------|
|---------|--------------|--------------|-------------|---------|----------------|

## Complete Minuteman Roller Systems

|   |                |  |                                       |   |  |
|---|----------------|--|---------------------------------------|---|--|
| 1 | <b>RMT8001</b> |  | Minuteman Front Grooved Roller System | 0 |  |
|---|----------------|--|---------------------------------------|---|--|

*Detail Description: Complete roller systems include roller and two brackets with bearings.:*

## Minuteman Rollers Only

|   |              |  |                               |   |  |
|---|--------------|--|-------------------------------|---|--|
| 2 | <b>RM513</b> |  | Minuteman Grooved Roller Only | 0 |  |
|---|--------------|--|-------------------------------|---|--|

*Detail Description: Use with Minuteman Roller Bracket System Only:*

## Other Parts Available

|   |              |  |                            |   |  |
|---|--------------|--|----------------------------|---|--|
| 3 | <b>RT821</b> |  | Bracket Assy - Front LH/RH | 2 |  |
|---|--------------|--|----------------------------|---|--|

*Detail Description: Includes RT8210 Bearing & Locking Collar, RMM606 Washer, R3219-5 Nut & RMM607 Screw:*

|   |                |  |                          |   |  |
|---|----------------|--|--------------------------|---|--|
| 4 | <b>RMMB157</b> |  | Bearing w/Locking Collar | 2 |  |
|---|----------------|--|--------------------------|---|--|

|   |               |  |                    |   |  |
|---|---------------|--|--------------------|---|--|
| 5 | <b>RT8210</b> |  | Block - Height Adj | 2 |  |
|---|---------------|--|--------------------|---|--|

|   |               |  |                                       |   |  |
|---|---------------|--|---------------------------------------|---|--|
| 6 | <b>RMM606</b> |  | Washer - Lock 3/8 Zinc Internal Tooth | 2 |  |
|---|---------------|--|---------------------------------------|---|--|

|   |                |                                                     |              |   |  |
|---|----------------|-----------------------------------------------------|--------------|---|--|
| 7 | <b>R3219-5</b> | 01-188-0820,<br>22-15-BJD,<br>22-15-BJKD,<br>3219-5 | Nut - 1/2-20 | 4 |  |
|---|----------------|-----------------------------------------------------|--------------|---|--|

|   |               |                                                                             |                       |   |  |
|---|---------------|-----------------------------------------------------------------------------|-----------------------|---|--|
| 8 | <b>RMM607</b> | 01-158-0610,<br>01-191-0820,<br>21-3900,<br>3220-5,<br>45-0170,<br>5/1/3220 | Nut - Jam 1/2-20 Zinc | 2 |  |
|---|---------------|-----------------------------------------------------------------------------|-----------------------|---|--|

|   |               |  |                                    |   |  |
|---|---------------|--|------------------------------------|---|--|
| 9 | <b>RMM608</b> |  | Screw - 8-32 x 5/16 SS Socket Head | 2 |  |
|---|---------------|--|------------------------------------|---|--|

|    |             |  |                  |   |  |
|----|-------------|--|------------------|---|--|
| 10 | <b>RMM3</b> |  | End Hub - 7/8 ID | 2 |  |
|----|-------------|--|------------------|---|--|

|    |               |  |                           |   |  |
|----|---------------|--|---------------------------|---|--|
| 11 | <b>RT821P</b> |  | Plate - For RT821 Bracket | 2 |  |
|----|---------------|--|---------------------------|---|--|

|    |               |  |                          |   |  |
|----|---------------|--|--------------------------|---|--|
| 12 | <b>RT821B</b> |  | Ball - For RT821 Bracket | 2 |  |
|----|---------------|--|--------------------------|---|--|

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



## **Replaces Toro Greensmaster 3100 Parts**

*SPA Cutting Unit - Models 04445, 04448 & 04450  
Minuteman Roller System*



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.