



# 1-1/4,1-1/2 Viton Gate Valve Repair Kiti

RGGTVRK015



## Details

1/2" - 2" Kit includes: 1-Stem O-ring, 1-Bonnet O-Ring, 1-Stem Bushing, 1-Stem Washer. 2-1/2" - 3" Kit includes: 1-Stem O-ring, 1-Seal Carrier O-ring, 1-Stem Bushing, 1-Stem Washer 4" Kit includes: 1-Stem O-ring, 1-Bonnet O-ring, 1-Stem Bushing,

## Specifications

Manufacturer	Sparks
Manufacturer's	GT-VRK-015
Model No	
Seal Type	Viton

## TURF MACHINERY SPARES LTD

3a Monument Way West Woking, GU21 5EN  
01483 764467

<https://turfmachinery.rrproducts.com/>