



3/4 PVC Viton Y-Pattern Valve Repair RGYVVRK007



Details

PVC Y-Pattern Valve Internal Repair Kit includes 1-Stem O-ring, 1-Seal Carrier O-ring, along with a factory assembled (required) internal component replacement unit consisting of Stem assembled with Seat & Seal Carrier components. Install in valve using existing valve Bonnet, Bonnet Nut, and Handle/Nut. True Union style valve kits include an additional 2-End Connector O-rings.

Specifications

Manufacturer	Spears
Seal Type	Viton