



NGK Spark Plug - R7376-10

RN4457



Replaces

Autolite	AR5383
Denso	IW01-31, IW06-31

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1