



NGK Spark Plug - BPR5ES

RN7734



Replaces

AC Delco	44NS, 44XLO, 44XLS, 45NS, 45XLS, 93742296, C42XLS, C44NS, CR44NS, R44CXLS, R44NS, R44XLS, R45NS
Autolite	2585, 3205, 3206, 3207, 4263, 4265, 55, 56, 65, 935, 945
Bosch	W8D, W8DC, W8DC0, W8DP, W9D, W9DC, WR8D, WR8DC, WR8DC4, WR9D, WR9DC
Champion	2415, 302, 302S, 38, 404, 404C2, 404S, 405, 405C2, 405S, 4405, 8405, 8405-1, 917C, N11Y, N11YC, N11YCC, N12Y, N12YC, N12YCC, N13Y, N14Y, N89Y, ON11Y, ON12Y, RN11Y, RN11YC, RN11YCC, RN12Y, RN12YC, RN12YCC
Denso	W16EP, W16EP-U, W16EPR-U, W16EXR-U
John Deere	M123089, M802138
MotorCraft	AGR42, AGR42C, AGR42CU, AGR52, AGS32C
R&R Products	R108-2557, R93-8584, RM123089, RM802138, RN7832
Toro	108-2557, 93-8584

Specifications

Manufacturer NGK

TURF MACHINERY SPARES LTD

3a Monument Way West Woking, GU21 5EN
01483 764467

<https://turfmachinery.rrproducts.com/>



NGK Spark Plug - BPR5ES

RN7734



Box Quantity 4
Package Quantity 1

Fits Models

- John Deere 220A Walk-Behind Greens Mower
- John Deere 220 Greens Mower
- John Deere Gator CS Utility Vehicle
- John Deere Gator CX Utility Vehicle
- John Deere Z960M ZTrak Zero-Turn Mower
- Toro Greensmaster 1000
- Toro Greensmaster 1600
- Toro Greensmaster 2000
- Toro Greensmaster 2600
- Toro Greensmaster 800
- Toro Greensmaster Flex 18
- Toro Greensmaster Flex 21
- John Deere Z970R ZTrak Zero-Turn Mower
- John Deere Z960A ZTrak Zero-Turn Mower
- John Deere Z960R ZTrak Zero-Turn Mower
- John Deere Z970A ZTrak Zero-Turn Mower

TURF MACHINERY SPARES LTD

3a Monument Way West Woking, GU21 5EN
01483 764467

<https://turfmachinery.rrproducts.com/>