

## Replaces Toro Workman 1100 Parts

*Traction Unit - Model 07252*

## Steering & Controls



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Workman 1100 Parts

Traction Unit - Model 07252

Steering & Controls



| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Order Quantity |
|---------|--------------|--------------|-------------|---------|----------------|
|---------|--------------|--------------|-------------|---------|----------------|

## Filters

|    |                  |                      |                        |   |  |
|----|------------------|----------------------|------------------------|---|--|
| 10 | <b>R108-3811</b> | 108-3811             | Element - Air Cleaner  | 1 |  |
| 10 | <b>R93-2195</b>  | 93-2195              | Baldwin Air Filter     | 1 |  |
| 10 | <b>RRF10125</b>  | 108-3808,<br>93-2195 | SilverGuard Air Filter | 1 |  |

## Guages and Controls

|    |                  |               |                                                      |   |  |
|----|------------------|---------------|------------------------------------------------------|---|--|
| 30 | <b>R114-3315</b> | 114-3315      | Solenoid -12 Vdc                                     | 1 |  |
| 31 | <b>R94-4208</b>  | 94-4208       | Hourmeter                                            | 1 |  |
| 32 | <b>R95-8999</b>  | 95-8999       | Switch - Headlight                                   | 1 |  |
| 33 | <b>R80-9330</b>  | 80-9330       | Alarm - Audio                                        | 1 |  |
| 34 | <b>R151541</b>   | R&R ON,<br>LY | Delta Seat Switch - Twist Mount 1 Pole Normally Open | 1 |  |

## Other Parts Available

|    |                  |                                                 |                          |   |  |
|----|------------------|-------------------------------------------------|--------------------------|---|--|
| 70 | <b>RMXB180GY</b> | 106-6672,<br>112-2923,<br>119-8829,<br>133-0577 | Milsco Seat XB180 - Grey | 1 |  |
|----|------------------|-------------------------------------------------|--------------------------|---|--|

*Detail Description: The Milsco XB180 bucket seat is designed with a sturdy vacuum formed waterproof vinyl cover that will not crack or peel. Ergonomic foam cushions ensure operator comfort. Features a durable blow molded plastic frame. Allows for an operator presence switch. Central drain hole prevents water build-up. 19 inch high-back seat will replace both original 16in and 19in high-back seats. Seat: 18.75in W x 18.8in H. Grey. Made in U.S.A.<BR>Please note: Due to excessive air freight charges, this item will be shipped ground freight.:*

|    |                 |                                 |                                      |   |  |
|----|-----------------|---------------------------------|--------------------------------------|---|--|
| 71 | <b>R98-1471</b> | 93-5212,<br>94-3500,<br>98-1471 | Steering Wheel Assy - 14 in Incl Cap | 1 |  |
| 72 | <b>R98-1468</b> | 98-1468                         | Cap - 14" Steering Wheel             | 1 |  |
| 73 | <b>R95-5806</b> | 95-5806                         | Bracket-Mounting                     | 1 |  |
| 74 | <b>R99-7420</b> | 100-8493,<br>99-7420            | Plug-Hole                            | 1 |  |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



## Replaces Toro Workman 1100 Parts

*Traction Unit - Model 07252*

*Steering & Controls*



| Item No | R&R Part No.       | OEM Part No.                                                | Description                      | Qty Req | Order Quantity |
|---------|--------------------|-------------------------------------------------------------|----------------------------------|---------|----------------|
| 75      | <b>R104-8300</b>   | 104-8300,<br>104-8300 ,<br>119-4041                         | Locknut - 5/16-18 Flanged Y/Zinc | 2       |                |
| 76      | <b>R92-5018-03</b> | 92-5018,<br>92-5018-03                                      | Clamp-Battery                    | 1       |                |
| 77      | <b>R87-9400</b>    | 104-0498,<br>87-9400                                        | Valve - Vacuator                 | 1       |                |
| 78      | <b>R2412-133</b>   | 01-651-0160,<br>2412-133                                    | Clamp                            | 1       |                |
| 79      | <b>R3234-11</b>    | 3234-11                                                     | Bolt - Hex Washer HD             | 1       |                |
| 80      | <b>R150848</b>     | 100-4928,<br>106-7848,<br>110-0413,<br>110-9720,<br>95-8910 | Belt-Seat                        | 1       |                |
| 81      | <b>R3274-105</b>   | 3274-105                                                    | Screw - Button HD Soc Cap        | 1       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.